

Oil Field Environmental Incident Summary

Incident: 20141017114440 **Date/Time of Notice:** 10/17/2014 11:44

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: UNNI 21X-27B

Field Name: MIDWAY

Well File #: 23404

Date Incident: 10/16/2014 **Time Incident:** 0730

Facility ID Number:

County: WILLIAMS

Twp: 157

Rng: 96

Sec: 27

Qtr:

Location Description:

Submitted By: Kaylan Dirkx

Received By:

Contact Person: Kaylan Dirkx
P.O Box 1589
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	8	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None-spill was contained within the lined metal berm.

Areal Extent:

Potential Environmental Impacts:

None-spill was contained within the lined metal berm.

Action Taken or Planned:

Water dump was repaired.

Wastes Disposal Location: 8 bbls recovered and returned to the production tanks. Indian Hills

Agencies Involved:

Updates

Date: 10/18/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location within the diking according to the report. NDIC retains oversight.